



#### EXPLANATION

- MW-5 ☒ Monitoring Well (destroyed)
- VP-1 ✎ Vapor Well (destroyed)
- FB-1 ✎ Former Verification Soil Boring (1999)
- BH-G • Soil Boring (Pre-1999)
- B-3 ⊕ Exploratory Boring (October, 2003)

N:\CADD\Retail and Terminal\9-0049\SAIC siteplan 9-0049.dwg  
 Basemap from Geoconsultants, Inc. and RRM, Inc.



Chevron Station 9-0049  
 401 Leavesley Road  
 Gilroy, California

SITE PLAN

FIGURE:  
 2  
 PROJECT:  
 90049